APPLICATION FOR SUPPLEMENTAL PERMIT TO MODIFY SITE OPERATION SCA/BARTON LANDFILL

INTRODUCTION/BACKGROUND

The SCA/Barton Landfill, located in a portion of the Southeast Quarter of Section 5, Township 4 North, Range 8 West in Madison County, Illinois is rapidly depleting on-site cover material. It will become necessary to obtain cover material from an off-site source for daily and intermediate cover for the balance of filling operations in the Phase III Fill Area, and for final cover in the Phase III and IV Fill Areas. Request is herein made for Supplemental Permit to use off-site material for these remaining cover requirements.

The remaining life of the permitted landfill site, as of August 1, 1981, is projected to be approximately twelve months based on an average daily refuse receipt volume of 1000 cubic yards per day and a six day work week operation. The associated daily and intermediate cover material requirement is approximately 55,000 cubic yards. The final cover requirement is approximately 60,000 cubic yards.

The proposed off-site source is an adjacent tract of 30 acres, more or less, located immediately west of the permitted landfill site as shown on the attached drawing number 74-119C-CM-1. Upon receiving the requested Supplemental Permit, SCA would execute an Option-to-Purchase this tract from Ruth M. Newton, the current owner.

Drawing number 74-119C-CM-1 indicates the topographic conditions on the permitted landfill site and the proposed off-site cover material tract as of June 10, 1981. Also shown are the property boundaries and the soil boring locations for the proposed off-site cover material tract.

US EPA RECORDS CENTER REGION 5

SOILS INVESTIGATIONS

Based upon available Illinois State Geological Survey maps and publications, the following geologic units are present regionally and are expected to exist locally at the site:

Peoria Loess

The Peoria Loess is a light yellow-tan to grey fine sandy silt existing in thicknesses ranging from 15 to 50 feet along portions of the bluffs. The loess thins away from the bluffs and grades into brownish-grey clayey silt locally.

Roxana Silt

The Roxana Silt is primarily loess, but contains some sand and commonly contains a colluvium of sand, silt and clay at its base. It varies in color from pinkish-tan to yellow-grey.

Vandalia Till Member; Illionian Glasford Formation

The Vandalia Till is a sandy, grey compact glacial till.

Mulberry Grove Silt Member; Illinoian Glasford Formation

The Mulberry Grove Member is described as a thin, lenticular unit of calcareous silt with local lenses of sand and gravel.

Smithboro Till Member; Illinoian Glasford Formation

The Smithboro Till is a grey till which contains higher silt content than does the Vandalia Till, and has a higher expandable content.

Five soil borings, located as shown on Drawing Number 74-119C-CM-1, were completed by John Mathes & Associates, Inc. at the subject site. The geologic units identified from these borings are summarized on the following figure. The actual boring logs are also attached.

It is apparent that as much as 35 feet of loess exists in the higher elevations of the site, ranging to less than 6 feet in the lower elevations. The upper 10 to 25 feet is bron in color and the lower portion is brownish grey to grey, with differing soil properties. The upper part is interpreted to represent the Peoria Loess, and the lower part, the Roxana Silt. The borings show from zero (0) to nine (9) feet of silty clay at the top of the column, overlain by a foot of topsoil, which is considered to have resulted from the admixture of slopewash during the last stages of loess deposition.

Underlying the loess are 6 to 16 feet of till. Grain size and stratigraphic position indicate that the till is the Vandalia Till Member of the Galsford Formation. This unit is underlain by interglacial sediments including lacustrine clays and fluvial sands and silts, all of which are considered to belong to the Mulberry Grove Silt Member. Till was encountered below these deposits and likely is the Smithboro Till Member of the Illinoian Glasford Formation (see attached Geologic Columns).


SITE DEVELOPMENT & OPERATION

Under normal circumstances, SCA owned equipment will be used for excavation, hauling and placement of all cover material obtained off-site at the subject site. The currently available equipment on-site includes: 1-dozer, 1-scraper, 1-end loader and 1-road grader. When necessary, additional equipment will be rented for final cover application. However, given favorable weather conditions, 40 - 50% of the operating time of equipment normally on-site can be dedicated to the application of final cover.

Final cover for the existing landfill would be obtained from the silty clay layer occurring immediately below the topsoil in the northern half of the subject site. Based on borings B-1A, B-2A, B-3A and B-11, this formation ranges in depth from

5 feet to 10 feet. Approximately 100,000 cubic yards of silty clay are available for use as final cover.

Daily cover and intermediate cover would be obtained from the Peoria Loess layer located beneath the silty clay layer in the northern half of the site, and below the topsoil in the southern half of the site. Ten to twenty-five feet of this material can be found over the entire site, providing an excess of 500,000 cubic yards of daily and intermediate cover material.



RECORD OF SUBSURFACE EXPLORATION

PROJECT Barton Landfill Addition BORING 1A



1	1]	<u> </u>	Τ	T .	_		1EAR	STR	ENG	ТН, '		
		(£	3E	و	ဟူ	DESCRIPTION OF	\S	(cms/sec)	• •			_ 02 1.0	/2 — 1.1	5		ວ ບ 2 2
		ОЕРТН (FT.)	SAMPLE	SAMPLE	NOTES	MATERIAL	BLOWS	ms/s			- 	 	- →	·		
		8			_	SURFACE ELEVATION 490.9	"	K (c	+ -		NATE	<u>-</u> •	, <u>co</u>	ONTE	<u>N1. 3</u>	• i
S	le.					Br Si CLAY w/Roots, TOPSOIL									士	土
Roberts	Maxeiner					Brown Silty CLAY w/Silt					1				\perp	1
200	May					Pockets, Oxidized Spots, Stains, Concretions, Trace				-	+-	╂╌┤	\vdash	-	+	+
		- 5 -	1	SS	·	Fine Sand	4-8	1 1			土		口			土
8	E E					•		1		-	+	\vdash	\vdash	 	+	+
DRILLED BY	LOGGED BY	\vdash				Brownish-Gray Clayey SILT	1				+	-	H		+	+
DA	۲۵					w/Oxidized Spots, Stains, Trace Fine Sand					T	\Box	П	\Box	\bot	Ţ
		-10-	2	3·T	Adv. 30'' Rec . 28''				-	$\vdash \vdash$	+	H	+	\dashv	+	+
			3	SS			7-7	7-7 5.9×			1		П	\Box	7	1
		\vdash						10-9	\vdash	b	+	H		\dashv	+	+
4-14-81			4	SS			4-5				90		口		士	Ī
1-1	Yes	15						1			+-		\vdash	\dashv	\dashv	4-
											十	\vdash	\vdash		+	+
<u>_</u>											1			\Box	1	\bot
[]	ETE	-20-	5	SS			2-3]		$\vdash \vdash$	ф_	\vdash	\vdash	-+	+	+
DATE DRILLED	PIEZOMETER										土				士	土
ă										\Box	T		П		$\overline{+}$	Ţ
			6	SS		-Brown @ 24.0'		-		0	+-	╂┤	\vdash	\dashv	+	+
	Auger	-25-	٥	33		-Gray Below 29.0'	2-4	-{							士	土
	Ā									$\vdash \downarrow$	+-	\vdash	$\vdash \vdash$		+	+
	Hollow									$\vdash \uparrow$	+	H	\vdash	\dashv	十	十
994-81	포	-30 -	7	3Т	Adv. 30"			4.3×			工		П	\Box	\top	Ţ
8	8				Rec. 26.5"	,			\vdash	$\vdash \vdash$	+-	\vdash	\vdash	+	+	+
	KET		8 -	SS			2-3	_		0 /	1				士	土
1 ≥ 3 3	Đ <u>X</u>				!		ļ <u>.</u>	-		$\vdash \downarrow$		\square	\vdash	+	\dashv	\bot
CONTRACT	DRILLING METHOD	-35	9	SS		Cont'd	2-3		H	0	+-	\vdash	H	+	+	+
]	٠ ب		GROUI	ND WAT	TER DEPTH	AT COMPLETION 38.5' AFTER 2	4 hrs.	25.5'		FTER	66	hr	 §_		24	<u>ـــ</u>

SCALE 1" - 5.01

——JOHN MATHES & ASSOCIATES, INC.—

				RECORD OF SUBSURFACE E	XPLORATIO	N				Г	~	7	
PROJ	ECT_	В	larton La	andfill Addition	BORING	<u>1A</u>	(Coi	<u>nt</u> 'd		JOHN 6 ASSO	MATI	HES INC	
DEP ТН (FT.)	SAMPLE	SAMPLE	NOTES	DESCRIPTION OF MATERIAL	BLOWS	DRY UNIT WEIGHT	\$\d 0	0.5	1.0	OP/2 -	1.5		0U/2
	9	55	Till	Gray Clayey SILT w/Oxidized Spots, Stains, Trace Fine Sand						1			1
- 40-	10	SS	Below 38.5' Wet	Brownish-Olive Silty CLAY w/Sand, Oxidized Spots, Stains, Trace Gravel	4-5					+			+
-45-	11	SS	Encoun- tered water @ 44.5'	-Yellowish-Brown Below 44.0'	3-4	ļ		q					+
- 50-	12	SS		тов	14-19								
								+		+	+-		+

Maxeiner Roberts DRILLED BY __ LOGGED BY 4-14-81 Yes DATE DRILLED. PIEZOMETER - 55-DRILLING METHOD HOLLOW Auger CONTRACT 994-81 **GROUND WATER DEPTH AT COMPLETION** AFTER _ AFTER_

5.0' SCALE 1" -_

JOHN MATHES & ASSOCIATES, INC.

RECORD OF SURSURFACE EXPLORATION

•		PROJ	ECT .	Ba	erton La	ndfill Addition	BORING					Ϋ́ο	HN P	ATH	S c	
ĺ	į	_	 	, 	1	T		T :	SHEAR STRENGTH, TSF							
		DEPTH (FT.) SAMPLE	SAMPLE	SAMPLE	NOTES	DESCRIPTION OF	BLOWS	(cms/sec)	5 \ 0 	0.5	1	0 P	1.5		20	2.5
			SA SA	8	2	MATERIAL	BL	l	PL + -	WATE		ATER - CON				,
S	er	-	 -			SURFACE ELEVATION 496.6		×		20	+	<u>"</u>	50	-+	-	100
Roberts	Maxeiner					Br Si CLAY w/Roots, TOPSOIL Brown Silty CLAY w/Oxidized Spots, Stains, Trace Root Holes								+	+	
		-5-	1	S,S		Brown Clayey SILT w/Oxidized Stains	4-2							1	1	
DRILLED BY	ΒY	<u> </u>		<u> </u>					-	\vdash	+-	\vdash	\vdash	+	+	+-
	LOGGED BY													\downarrow	1	_
۵	ונ		2	SS		-Trace Root Holes @ 9.0'	5-5			-	+-1		\dashv	+	+	+
3.1		- 10-			Damp To									\perp	工	
	}										\perp		\vdash	\dashv		1
		<u> </u>							-	\vdash	+	\vdash	\vdash	+	+	+
			3	SS			3-5	9 1X	-	\vdash	b	П	\sqcap	+	+	+
4-16-81	10	- 15-			Moist			10-7						I	\perp	
4	Yes								<u> </u>	-	\downarrow	\square		\dashv	\bot	
						-Trace Fine Sand Below 19.0'			-	-	+-	$\vdash \dashv$	\dashv	\dashv	+	+-
DAILLED	E			-		Trace Time Saint Below 13.0		1	-		+	$\vdash \vdash$		+	+	+
DAM	PIEZOMETER	- 20-	4	SS	ļ		4-5								工	
DATE	EZO				Í									\bot		1
Ã	٦	<u> </u>							-	-	+		\vdash	\dashv		+
		- -	_			-w/Oxidized Spots Below 24.0	4-4	1	-	-	-		-	+	+	+
	-e	25-	5	SS				-					\Box	+		\perp
	Auger													\Box	I	I
	- 1								_	-	-	$\vdash \vdash$				+
_	Hollow	 -			1	-Brownish-Gray Below 29.0'	<u> </u>	}	-	$\vdash \vdash$	+-	\vdash	\vdash	\dashv	+	+
8-466	•	-30-	6	SS		•	2-3		-	$\vdash \vdash$	10	\vdash	\vdash	+	+	+
66	, 1]		1			}						士	工	
, ,	MET			Ì	1	Brownish-Gray Si Sa CLAY w/ Oxidized Spots, Stains			_		\Box	Ш		\bot		1
PAC	NG.	<u> </u>		<u> </u>	}	-Trace Gravel @ 34.0'		}	 	├-}-				\dashv	+	+
CONTRACT	DRILLING METHOD	- 35-	7	SS		Cont 'd	3-3							\pm	\pm	土

-30-Brownish-Gray Si Sa CLAY w/ Oxidized Spots, Stains -Trace Gravel 👂 34.0' 7 SS 3-3 Cont 'd AFTER 16 hrs 45.3' AFTER Dry **GROUND WATER DEPTH AT COMPLETION** SCALE 1" - 5.0' JOHN MATHES & ASSOCIATES, INC. —